

NEO LTO-5 WWNN & WWPN Preservation

May 2013

Preface

This Technical Information Bulletin documents the procedure for preserving the current World Wide Node Name (WWNN) and World Wide Port Name (WWPN) when updating IBM LTO-5 tape drive firmware. This bulletin only applies to NEO 2000e, NEO 4000e, and NEO 8000e tape libraries using IBM LTO-5 tape drives.

Prerequisites

Prior to performing this procedure, ensure that you have the following:

- Current release of NEO E-series library firmware for your library:
 - NEO 2000e/4000e Version 2.1.026 or later.
 - NEO 8000e Version 7.1.050 or later.
- Current release of IBM LTO tape drive firmware for the tape drives in your library
 - IBM LTO-5 Version D2A0 or later.

The current release of firmware for the NEO E-series libraries and IBM LTO-5 tape drives can be downloaded from the Overland Storage ftp site at <u>ftp://ftp.overlandstorage.com/Firmware</u>.

Overview

Upgrading IBM LTO-5 tape drive firmware from Version BBN2 to a newer version changes the default WWNN and WWPN of the tape drive. Some customers may want to maintain the original WWNN and WWPN. In order to preserve the original WWNN/WWPN, the following procedure should be performed.

Procedure

- **1.** Verify that the **current release** of library firmware is installed. Upgrade the library firmware if necessary.
 - NEO 2000e/4000e: Version 2.1.026 or later.
 - NEO 8000e: Version 7.1.050 or later.
- 2. Determine the current WWNN and WWPN of the tape drives in your library.

The current tape drive WWNN and WWPN can be displayed using the Web Management Interface of the library and navigating to **Status > Full Drive Status** for the associated tape drive.

Drive 1 Status (Complete) Drive Identification							
Drive Type	IBM LTO5 fibre channel						
Serial Number	1068081197						
Vendor ID	IBM						
Product ID	ULTRIUM-TD5						
Revision Level	BBN2						
Firmware Version							
World Wide Node Name	50:05:07:63:12:4C:53:40						
World Wide Port 0 Name	50:05:07:63:12:4C:53:41						
Port 0 Current Topology	Loop						
Drive Status							
Media Status	Not Present						
Cleaning Status	None						
Error Condition	No						

Depending on your SAN environment, you may also be able to display the WWNN and WWPN of the tape drives using your Host Bus Adapter utility or Fibre Channel switch (Name Server). The following example shows a view from the Qlogic SANsurfer FC HBA Manager.



- **3.** After you have recorded the WWNN and WWPN values that you want to preserve, log in to the Web Management Interface of the library, navigate to **Setup > Drive Configuration**, and choose the appropriate **Drive Number** to open the configuration screen.
- **4.** Select the **Custom** option for both World Wide Port 0 Name and World Wide Node Name, enter the corresponding **values** recorded in the previous step, and then click **Submit**.



- **5.** Repeat Steps 3–4 for **each tape drive** in the library.
- **6.** After you have configured the Custom WWNN and WWPN for each tape drive in the library, proceed with the **tape drive firmware update** process.

The tape drive firmware can be updated using the Web Management Interface or the IBM Tape Diagnostic Tool (ITDT).

7. After the tape drive firmware update process is completed for each tape drive, log in to the Web Management Interface to verify that the new **firmware version** and the previously configured **Custom WWNN and WWPN** are reported correctly.

Drive 1 Status (Complete) Drive Identification						
Drive Type	IBM LTO5 fibre channel					
Serial Number	1068081197					
Vendor ID	IBM					
Product ID	ULTRIUM-TD5					
Revision Level	D2A0					
Firmware Version						
World Wide Node Name	50:05:07:63:12:4C:53:40					
World Wide Port 0 Name	50:05:07:63:12:4C:53:41					
Port 0 Current Topology	Loop					
Drive	Status					
Media Status	Not Present					
Cleaning Status	None					
Total Cleanings	2					
Total Loads	181					
Error Condition	No					

Depending on your SAN environment, you may also be able to display this information using your Host Bus Adapter utility or Fibre Channel switch (Name Server). The following example shows a view from the Qlogic SANsurfer FC HBA Manager after the update.

🛓 SANsurfer F	C HBA Manage	r							
<u>F</u> ile H <u>o</u> st <u>V</u> i	ew <u>S</u> ettings	<u>W</u> izards	<u>H</u> elp						
0			$\langle 0 \rangle$	7	<u>ida</u>	\square	ĊĮ		æ
Connect	Configure	App Events	HBA Event	ts Collect	Monitor	Diags	Refresh		QLOGIC •• Blacks Profession
FC/CNA HBA]			Information	LUN List				
				Hostnam	e se-w2k8	-64-3494/10.2	20.34.94	Node Name	20-00-00-E0-8B-1C-1A-6D 📥
me se-w2k8-64	-3494/10.20.3	4.94:Good		HBA Mod	lel QLA2342	2		Port Name	21-00-00-E0-8B-1C-1A-6D
Port 1"Good	12G000			HBA Port	t 1			Port ID	00-00-01
🚈 Tape (50-0	5-07-63-12-4C	-53-41):Onlir	ne, Diag I	General Inform	nation				
- 📋 LUN (0)				Product Ven	dor: IBM		Product I	D: UL	_TRIUM-TD5
LUN (1)				Product Rev	ision:D2A0		Node Nar	ne: 50	-05-07-63-12-4C-53-40
Port 2::Good				Port ID:	00-00-2	6	Port Nam	ne: 50	-05-07-63-12-4C-53-41
				Serial Numb	er: 106808	1197			

This completes the procedure for preserving the current World Wide Node Name (WWNN) and World Wide Port Name (WWPN) when upgrading the IBM LTO-5 tape drive firmware.