RDX® QuikStation 8 Firmware Release Announcement

May 2018

RDX QS8 Firmware Version 01.004.02

This firmware version is compatible with all previous code versions.

OS (DOM) version: 02.001.03.

The OS version has not changed.

Fixes:

Fixed issue where RDX QuikStation fails to boot successfully after loading 01.004.01 firmware version because of error in identifying the QuikStation boot device.

RDX QS8 Firmware Version 01.004.01

This firmware version is compatible with all previous code versions.

OS (DOM) version: 02.001.03.

The OS version has not changed.

Fixes:

- Fixed issue where RDX QuikStation incorrectly reports an RDX media error condition by turning on the amber LED.
- Fixed issue where the Remote Management Console incorrectly reports that the RDX media is write-protected.
- Fixed issue where RDX QuikStation dock reports as "empty" in the Remote Management Console when an RDX media is loaded.
- Security fixes for CVE-2016-0800, CVE-2016-2108, and CVE-2016-2183.

RDX QS8 Firmware Version 01.003.06

This firmware version is compatible with all previous code versions.

OS (DOM) version: 02.001.03.

The OS version has not changed.

Fixes:

- Fixed issue that disallowed Windows users the ability to eject a logical volume from their initiator connection.
- Fixed issue where all QS configurations would blink the disk LEDs continuously. This version, until otherwise addressed, only blinks the LEDs continuously when in a Logical Volume configuration.
- Fixed issue during upgrades that allows the script to delete the entire contents of any file in the /var/log directory or subdirectories that are larger than 100MB in size.

RDX QS8 Firmware Version 01.003.05

This firmware version is compatible with all previous code versions.

OS (DOM) version: 02.001.03.

The OS version has not changed.

Fixes:

- Fixed issue where internal log files can grow very large and cause the RDX QuikStation 8 to be inaccessible via the Remote Management Console.
- Fixed issue where read performance is degraded when the QuikStation 8 is configured as a Tape Library logical device type.

Improvements:

- Added cartridge auto-mount feature for the RDX Logical Volume device type.

RDX QS8 Firmware Version 01.003.03

This firmware version is compatible with all previous code versions.

OS (DOM) version: 02.001.03.

The OS version has not changed.

Fixes:

- Fixed issue where fans rotating slower than 800 RPM are not logged as failing.

RDX QS8 Firmware Version 01.003.02

This firmware version is compatible with all previous code versions.

OS (DOM) version: 02.001.03.

The OS version has not changed.

Fixes:

- Fixed issue where media inserted into docks 3 or 4 are not seen when the QuikStation 8 is configured in Hybrid Configuration.
- Fixed issue where QuikStation 8 configured in Tape Automation Configuration mode cannot format or read RDX cartridges of greater than 2TB capacity.

OVERLAND TANDBERG

9112 Spectrum Center Boulevard | San Diego, CA | 92123 USA
T 858.571.5555 | F 858.571.3664 | www.overlandstorage.com