

RDX[®] Manager Version 0.1.0.40 Release Announcement

December 2019

Preface

This Product Information Bulletin announces the release of the updated RDX Manager for Windows software utility version 0.1.0.40. This replaces version 0.1.0.33.

Models Affected

Use RDX Manager for Windows software utility version 0.1.0.40 with all RDX QuikStor® and RDX QuikStation® models.

Software Utility Version 0.1.0.40

Changes and Enhancements

- RDX Manager enables volume password protection for RDX QuikStor USB3.0 systems.
 - An Administrator can assign up to eight passwords with different read or write access options for the entire volume.
 - Password protection can be used with any RDX media in RDX USB3.0 systems with firmware version 0283 or higher.
 - Password protected RDX media is compatible with RDX SATA III systems.
- RDX Manager improvements include:
 - Improved communication when changing SATA III modes.
 - Enhanced functionality with the Command Line Utility for non-Admin users.
 - · Addressed crash issue when "Scan for RDX Drives" button is clicked in rapid succession.
 - Enhanced functionality for RDX QuikStor in Fixed-Disk Mode.
 - Improved the RDX Manager uninstall process.

Previous Software Utility Version 0.1.0.33

Changes and Enhancements

- Implemented fix for firmware updates that did not work when the RDX Manager GUI is configured for the Japanese language.
- Implemented Japanese language translation changes.



Previous Software Utility Version 0.1.0.30

Changes and Enhancements

- Added the Japanese language in RDX Manager UI.
- Updated the End User License Agreement (EULA).
- Implemented RDX media eject functionality in the command line utility.
- Implemented a silent install option for RDX Manager software.
- Updated the RDX system summary report to include RDX media encryption status.
- Improved auto-uninstall process for previous version of RDX Manager and RDX Utility.
- Enhanced RDXmon event logging functionality.
- Enhancement for RDX Manager software encryption support: Added a check to MBR partitioning to ensure the disk signature is not zero.

Previous Software Utility Version 0.1.0.28

Changes and Enhancements

- Added the following languages in RDX Manager UI: German, French, Italian, Spanish, Portuguese, and Chinese.
- · Added command line function to create an RDX system summary report in XML file format.
- Implemented fix to address an intermittent RDX media eject failure issue.
- Improved error messaging for RDX Manager software install failures.
- Implemented fix for issue where Drive Policy is not displayed in the Status window.
- Implemented fix to ensure the Encryption window cannot be closed while an operation is in progress.
- Implemented fix to ensure that a Windows Explorer right-click eject of RDX media does not generate warning message in the Windows Event Viewer Application log.

Previous Software Utility Version 0.1.0.25

Changes and Enhancements

- Automatically change the Device Removal Policy for RDX USB drives to Optimize for Performance (or Better Performance).
- Cartridge Model field in the Drive List window revised to Cartridge Size.
- Improved RDXmon event logging.

Previous Software Utility Version 0.1.0.22 – Initial Release

Changes and Enhancements

- RDX Manager for Windows software utility is replacing all current RDX utilities and is the new platform for new releases and future Windows platform support.
- Supported OS versions: Windows 7, Windows 8, Windows 10, Server 2008, Server 2012, Server 2012R2, Server 2016.
- New main screen layout with improved user experience.
- New RDX Encryption Tab with support for RDX SATA III Hardware Encryption and Multi Password and data access/protection configuration options.



- Online help integrated.
- Improved diagnostic and service features.
- Online check for new RDX firmware support and RDX Manager software releases.
- New RDX media Repartition and Format option.
- New RDX media eject feature.



Tandberg Data Feldstraße 81 44141 Dortmund, Germany

TEL +49 231 5436 0 FAX +49 231 5436 111

10400935-001